

BUREAU VERITAS

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GÉNÉRALE DE L'AVIATION CIVILE

*Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of "Consigne de Navigabilité"  
Réf. : 75-040-011(B)R1  
In case of any difficulty, reference should  
be made to the French original issue.

## AEROSPATIALE SA 341 G helicopters

Checking and Lubricating the  
Oil Pump/Hydraulic Unit Drive Gear

Subsequent to reports of in-service wear, the operations described in AEROSPATIALE SA 341 S.B. n° 05-09 have been rendered mandatory for SA 341 G aircraft :

- a)- Dimensional check on the hydraulic unit drive gear splines (effective only for the BRONZAVIA blocks on which AMS 07-0779 has not been embodied).
- b)- Lubrication time limit added for this coupling (effective for all types of unit).

These operations are to be performed as per MET work card n° 29.10.603 at intervals not exceeding 400 flying hours.

\_\_\_\_\_

Cf. : B.S. AEROSPATIALE SA 341 n° 05-09

\_\_\_\_\_

The present revision I cancels and replaces  
the original AD 75-040-011(B) dated February 18, 75

EFFECTIVE DATE : SEPTEMBER 30, 1989

September 20, 89

AEROSPATIALE SA 341 G helicopters

Ref. : 75-040-011(B)R1