

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE
RELEASED BY THE SECRETARIAT GENERAL
FOR CIVIL AVIATION

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness (see decree regarding airworthiness requirements for civil aircraft).

AEROSPATIALE HELICOPTERS - SA 330 PUMA (ALL MODELS)

OPERATIONAL EQUIPMENT - "AIR EQUIPMENT" FIXED OR VARIABLE SPEED EXTERNAL
HOLSTS, TYPE 76.360.100 AND 76.360.110.01

To ensure satisfactory operation of the pyrotechnic cable cutter, the following steps have been rendered mandatory for the aircraft fitted with the above-referenced hoists :

- On receipt of the present Directive, ascertain that the electric cables are correctly connected to the cutter and check for correct operation of the installation, as instructed in AEROSPATIALE Service-Bulletin SA 330 PUMA N° 45.06

Note :

On this occasion, figure 6, page 10, chapter 45.50 of the Maintenance Manual should be corrected as indicated in Service-Bulletin 45.06. This correction is only applicable to the maintenance documentation as the equipment concerned has been originally supplied to the standard specified.

AEROSPATIALE SERVICE BULLETIN SA 330
PUMA No 45.06 refers.

Translation of "Consigne de Navigabilité"
Réf. 75-77-8

In case of any difficulty, reference
should be made to the French original text.

Date : 22.4.75

Material : AEROSPATIALE HELICOPTERS

Reference : 75-77-8