

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE  
RELEASED BY THE  
"DIRECTION GENERALE DE L'AVIATION CIVILE"

The inspections or modifications described below are mandatory. Failure to comply with Airworthiness Directives entails suspension of the Certificate of Airworthiness.

Translation of "Consigne de Navigabilité"  
Réf. : 78-225-36(B)  
In case of any difficulty, reference  
should be made to the French original text.

AEROSPATIALE HELICOPTERS ALOUETTE III

(TYPES SE3160 - SA316B - SA316C - SA319B)

Attachment of tail gear box strut assembly  
to frame 8 of tail boom

To prevent a possible fatigue failure under the head of the TGB strut lower attaching bolt the steps described in AEROSPATIALE Service Bulletin ALOUETTE n° 01.45 (check for condition of TGB strut attaching bolts 51103P6Q.42.5 BCL on frame 8 and conformance of bushes 3160S.23.11.654 with design standard) have been rendered mandatory.

These measures are to be applied within the 20 hours of light following the date at which the present directive has become effective.

---

Ref. : AEROSPATIALE SERVICE BULLETIN ALOUETTE n° 01.45

---

DATE OF EFFECTIVITY : DECEMBER 13th 1978

Date : 12/6/1978

Material : AEROSPATIALE HELICOPTERS  
ALOUETTE III

Reference : 78-225-36(B)