

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

RELEASED BY

"DIRECTION GENERALE DE L'AVIATION CIVILE"

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 79-231-28(B)
In case of any difficulty, reference
should be made to French original issue

AEROSPATIALE HELICOPTERS SA 330 PUMA (ALL MODELS)

IMPROVING THE LUBRICATION OF EYE BOLT BEARINGS ON BLADE HORN

ASSEMBLY P/N 330 A 31 1369 00 AND 01 (POST AMS 07 42 090)

(the present directive is applicable to SA 330 helicopters fitted with main rotor head P/N 330 A 31 0020 and 330 A 31 0030 all dash numbers)

Several cases of damage to eye bolt bearing P/N 330 A 31 9820 attributed to a fretting corrosion phenomenon have been experienced in service. In consequence, the incorporation of a modification aimed at improving the lubrication of bearings described in AEROSPATIALE PUMA service bulletin n° 65.30 has become mandatory.

This operation shall be carried out within the 50 hours of operation following the date at which the present directive has become effective.

Ref. : AEROSPATIALE SERVICE BULLETIN PUMA N° 05.30

DATE OF EFFECTIVITY : 28. NOVEMBER 1979

Date : 21/11/1979

Material : AEROSPATIALE HELICOPTERS
SA 330 PUMA (ALL MODELS)

Reference : 79-231-28(B)