

AIRWORTHINESS DIRECTIVE

RELEASED BY

"DIRECTION GENERALE DE L'AVIATION CIVILE"

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 80-164-7 (B)
In case of any difficulty, reference
should be made to French original issue

AEROSPATIALE HELICOPTERS SA 365 C/C1/C2 DAUPHIN

MAGNETIC PLUG ON ENGINE OIL SYSTEM WITH WARNING INSTALLATION
EVOLUTION OF STANDARD AND MODIFICATION OF OPERATING INSTRUCTIONS

The installation of magnetic plug on the engine oil system, fitted with a warning installation is required by Airworthiness Directive 79-253-6 (B) dated 19.12.79 for SA 365 C and C1 helicopters. This installation has been incorporated in the basic standard of SA 365 C2 helicopter.

Based on the experience gained in service, the decision was made to replace the red warning light with an amber light with modification of the associated operating instructions.

The installation of an amber light in accordance with AEROSPATIALE Service Bulletin DAUPHIN No 77.01, Issue 2, shall be performed on 31st march 1981, at the latest.

After installation of the amber light, the operating instructions applicable to this new standard will form the following revisions :

- No 5 of august 1980 to SA 365 C/C1 flight manual
- No 2 of august 1980 to SA 365 C2 flight manual

Ref. : AEROSPATIALE SERVICE BULLETIN SA 365 DAUPHIN
NO 77.01, ISSUE 2, or approved subsequent
revision.

DATE OF EFFECTIVITY : 3RD SEPTEMBER 1980

Date : 8.27.1980

Material : AEROSPATIALE HELICOPTERS
SA 365 C/C1/C2 DAUPHIN

Reference ; 80-164-7 (B)