

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

RELEASED BY

"DIRECTION GENERALE DE L'AVIATION CIVILE"

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 80-165-14 (B)
In case of any difficulty, reference
should be made to French original issue

AEROSPATIALE HELICOPTERS AS 350 B ECUREUIL

MAGNETIC PLUG ON ENGINE OIL SYSTEM WITH WARNING INSTALLATION
EVOLUTION OF STANDARD AND MODIFICATION OF OPERATING INSTRUCTIONS

The installation of a magnetic plug on the engine oil system, fitted with a warning installation, is required by Airworthiness Directive 79.254.12 (B) dated 19.12.79.

Based on the experience gained in service, the decision was made to replace the red warning light with an amber light with modification of the associated operating instructions.

The installation of an amber light in accordance with AEROSPATIALE Service Bulletin AS 350 No 77.02, Issue 2, shall be performed on 31st march 1981 at the latest.

After installation of the amber light, the operating instructions applicable to this new standard will form the subject of revision No 5 of august 1980 to AS 350 B flight manual.

Ref. : AEROSPATIALE SERVICE BULLETIN AS 350 NO 77.02,
ISSUE 2, or approved subsequent revision.

DATE OF EFFECTIVITY : 3RD SEPTEMBER 1980

NOTE : Cancels and replaces same text previously issued under a wrong reference 80.165.34 (B) dated 8.27.80

Date : 8.27.1980

Material : AEROSPATIALE HELICOPTERS
AS 350 B ECUREUIL

Reference ; 80-165-14(B)