

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by Direction Générale de l'Aviation Civile

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 85-13-9(B)R1
In case of any difficulty, reference should
be made to the French original issue.

AEROSPATIALE HELICOPTERS DAUPHIN SA 365 N WIRE ANTENNA INSTALLATION FOR HF SSB RADIO.

The present Airworthiness Directive applies to AEROSPATIALE SA 365 N DAUPHIN helicopters, all serial numbers, which have not been modified in accordance with modification AMS 07.4733 or AMS 07.23B02.

To preclude hazards entailed by a possible rupture at the tension adjuster of the wire antenna, installing a safety attachment is rendered mandatory and must be performed within the next ten (10) flying hours following February 6, 1985 in conformance to the procedure stated in AEROSPATIALE Service Telex SA 365 N N° 01-05 (or a later approved revision) or according to an equivalent duly approved solution, unless already accomplished.

Ref. : AEROSPATIALE Service Telex SA 365 N n° 01-05.

CANCELS AND REPLACES A.D. 85-13-09(B) DATED JANUARY 30, 1985

EFFECTIVE DATE : FEBRUARY 12, 1986.

FEBRUARY 5, 1986

**AEROSPATIALE HELICOPTERS
DAUPHIN SA 365 N**

Ref. : 85-13-9(B)R1