

**BUREAU VERITAS**

## **AIRWORTHINESS DIRECTIVE**

released by Direction Générale de l'Aviation Civile

*Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of "Consigne de Navigabilité"  
Réf. : 85-37-10(B)  
In case of any difficulty, reference should  
be made to the French original issue.

### **AEROSPATIALE HELICOPTER SA 365 N DAUPHIN**

#### **LOCKING OF REAR SIDEGATE**

This Airworthiness Directive concerns AEROSPATIALE SA 365 N helicopters not equipped with slide doors and not embodying modification AMS 365A07.4546.

To prevent any risk of untimely in-flight opening of sidegates, the locking improvement modifications prescribed by AEROSPATIALE SA 365 N Service Bulletin n° 01-06 is rendered mandatory and must be embodied within the next 30 hours of operation following the effective date of the present Airworthiness Directive (unless already implemented).

---

Ref. : AEROSPATIALE SA 365 N Service Bulletin n° 01-06.

---

**EFFECTIVE DATE : MARCH 20, 1985**

**MARCH 13, 1985**

**AEROSPATIALE HELICOPTER  
DAUPHIN SA 365 N**

**Ref. : 85-37-10(B)**