

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by Direction Générale de l'Aviation Civile

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité"
Réf. : 85-85-12(B)
In case of any difficulty, reference should
be made to the French original issue.

AEROSPATIALE HELICOPTERS DAUPHIN SA 365 N

ENGINE FIRE EXTINGUISHER SYSTEM

A possibility of inverting connection of the tubings and non conformity of installation and identification of pyrotechnic cartridges and percussion heads, has been evidenced. In consequence, the following measures have been rendered mandatory (unless already complied with) :

- 1 - Prior to any flight, on the effective date of the present Airworthiness Directive, check and, if required, correct the connection of tubings on the engine fire extinguishing system, in accordance with the instructions given in paragraphs 1C (1) and 1C (3) (a) of AEROSPATIALE Service Bulletin SA 365 N n°01-10 (except if already complied with through the embodiment of AEROSPATIALE Telex Service SA 365 N n° 01-10 and Airworthiness Directive n° 85-57-11).
- 2 - Prior to any flight, on the effective date of the present Airworthiness Directive, check and, if required, correct the installation and colour identification of the pyrotechnic cartridges and percussion heads on the engine fire extinguishing system, in accordance with paragraphs 1C (2), 1C (3) (b) and 1C (3) (c) of AEROSPATIALE Service Bulletin SA 365 N n° 01-10.

Ref. : AEROSPATIALE SERVICE BULLETIN SA 365 N N° 01-10

Cancels and replaces AD 85-57-11(B) dated April 24,1985

EFFECTIVE DATE : JUNE 26, 1985

JUNE 19, 1985

**AEROSPATIALE HELICOPTERS
DAUPHIN SA 365 N**

Ref. : 85-85-12(B)