

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 91-041-030(B)

In case of any difficulty, reference should be made to the French original issue.

AEROSPATIALE SA 365 N helicopters

LUCAS AIR EQUIPMENT electric hoist

The present Airworthiness Directive applies to AEROSPATIALE SA 365 N helicopters equipped with the LUCAS AIR EQUIPMENT hoist installation, P/N 76375 (all types) or 76378 (all types).

1. In order to enable the pyrotechnic shearing squib to be reconnected (subsequent to disconnection due to possible untimely tripping), the following measure is rendered mandatory for aircraft which have not been modified per AMS 07-45B73 :
 - . within the next 50 flying hours and before April 1, 1991 at the latest, apply AEROSPATIALE SA 365 Service Bulletin N° 25-19 in full.
2. Every 500 flying hours or every 18 months (whichever limit is reached first), and every time the hoist or the hoist arm is removed, for aircraft modified per paragraph 1.C.1 of SA 365 S.B. n° 25-19 or modified per AMS 07-45B73, check the electrical bonding as per paragraph 1.C.2 of SA 365 S.B. n° 25-19.

Ref. : AEROSPATIALE SA 365 Service Bulletin n° 25-19

EFFECTIVE DATE : MARCH 16, 1991

March 6, 91

AEROSPATIALE
SA 365 N helicopters

91-041-030(B)