

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive*

Translation of 'Consigne de Navigabilité'  
Réf.: 91-068-039(B)  
In case of any difficulty, reference should be made to the French original issue.

## ATR 42 aircraft series 200 ; 300

Flight controls

This Airworthiness Directive applies to ATR 42-200, -300 and -320 aircraft, serial numbers 003 to 208, 213, 214, 218, 221, 225, 226 and 228.

The following steps are made mandatory in order to prevent failure of the rudder pedal connection rod :

- A. Before April 1, 1991, identify the make of the rudder pedal connection rod, following the instructions of S.B. ATR 42-27-0052.  
If the rod is a TAC rod, no further action is required.
- B. If the inspection required in paragraph A shows that a SARMA rod has been installed, before June 15, 1991 replace it by a TAC rod or a SARMA rod identified P/N 14132 C by the Constructor, following the instructions of S.B. ATR 42-27-0052.

Ref. B.S. ATR 42-27-0052

EFFECTIVE DATE : UPON RECEIPT

March 20, 91	ATR 42 series 200 ; 300	91-068-039(B)
--------------	-------------------------	---------------