

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 91-206-044(B)

In case of any difficulty, reference should be made to the French original issue.

AEROSPATIALE AS 332 helicopters

Landing gear actuator fairing

The present Airworthiness Directive applies to AEROSPATIALE AS 332 helicopters versions C, C1, L and L1 fitted with landing gear actuator fairings part numbers :

- 332A21.1032)
- 332A21.1033) all dash numbers
- 332A21.1501)

(not reinforced by modifications 332A07.23722 or 23723).

In order to prevent the loss of a fairing in flight, the following measures are rendered mandatory :

- Within the next 50 flying hours after the effective date of this Airworthiness Directive, then during each type "T" inspection, check the condition of the fairings in accordance with the instructions given in paragraph 1C(1) of AS 332 Service Bulletin n° 05.35.
- If necessary, according to the results of the check, repair within the next 50 hours after the check, in accordance with the instructions given in paragraph 1C(2) of the Service Bulletin.

Ref. : AEROSPATIALE AS 332 Service Bulletin n° 05.35

EFFECTIVE DATE : OCTOBER 12, 1991

October 2, 1991

AEROSPATIALE AS 332
Helicopters

91-206-044(B)