BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Altworthiness Directive applies except in accordance with the requirements of this Altworthiness Directive

Translation of 'Consigne de Navigabilité' Rét.: 91-214-042(B)

In case of any difficulty, reference should be made to the French original issue.

ATR 42 aircraft

Flight controls

This Airworthiness Directive concerns the ATR 42 series 200 and 300, serial numbers 003 to 207 inclusive.

In order to ensure correct attachment of tabs on the elevators, the following actions are made mandatory:

 Within the 300 flight hours following the effective date of this Airworthiness Directive, replace the elevator tab hinge lock nut pins according to the instructions of SB ATR 42-55-0005 unless this has already been done.

Inform the ATR Product Support of the results of the inspection.

Ref.: SB ATR 42-55-0005

EFFECTIVE DATE: OCTOBER 12,1991

October 2, 91 ATR 42 aircraft 91-214-042(B)