

BUREAU VERITAS

## AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive*

Translation of 'Consigne de Navigabilité'

Rét.: 91-248-046(B)

In case of any difficulty, reference should be made to the French original issue.

### AEROSPATIALE AS 332 helicopters

#### Fuel filter

The present Airworthiness Directive applies to AEROSPATIALE AS 332 helicopters, versions C, C1, L and L1, fitted with a "- 45 degrees C" fuel filter (P/Nos 4020P25.1 and.2).

Further to a report indicating failure of the stirrup clamp which secures the "- 45 degrees C" fuel filter bowl in operation, the following measures are rendered mandatory.

- 1/ Within the next 50 flying hours after the effective date of this Airworthiness Directive, remove the stirrup clamps which have logged more than 450 flying hours.
- 2/ Limit the operating time for the stirrup clamps to 500 hours.

Ref. : AS 332 Telex Service N° 01.32

EFFECTIVE DATE : DECEMBER 07, 1991

November 27, 91

AEROSPATIALE AS 332 helicopters

91-248-046(B)