

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 92-262-016(B)
In case of any difficulty, reference should be made to the French original issue.

ATR

ATR 72 series 100 and 200 aircraft

Outer wing

The present Airworthiness Directive applies to ATR 72 series 100 and 200 aircraft on which modification 3196 has not been embodied.

To prevent crack initiation and propagation from accidental damage created during the installation of fasteners at the forward and rear joint straps on the outer wing spars between ribs 13 and 14, following measures are made mandatory :

- Before December 31, 1993, inspect the fastener and, if no spot-facing has been performed add a shin and replace the fastener by ball nut, following the instructions of Service Bulletin ATR 72-57-1008.

REF. : Service Bulletin ATR 72-57-1008

EFFECTIVE DATE : DECEMBER 05, 1992

n/F

November 25, 1992

ATR
ATR 72 series 100 and 200 aircraft

92-262-016(B)