

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

**Translation of 'Consigne de Navigabilité' ref. : 94-117-001(B)
In case of any difficulty, reference should be made to the French original issue.**

AIRBUS INDUSTRIE

A330 Aircraft

Cargo compartment - Fire extinguisher distribution pipe

This Airworthiness Directive applies to AIRBUS INDUSTRIE A330 aircraft model -301 without AIRBUS INDUSTRIE modification 42451 or without AIRBUS INDUSTRIE Service Bulletin A330-26-3002.

In order to prevent, in case of fire in the FWD cargo compartment an incomplete discharge of the fire extinguisher agent contained in the N°2 fire extinguisher bottle due to the blocking of the pipe distribution located between the bottle and the HALON filter, the following measures are rendered mandatory on the effective date of this Airworthiness Directive, unless already accomplished :

- Within 450 flight hours on the effective date of the Airworthiness Directive, replace the fire extinguisher distribution pipe and their attachments in accordance with the instructions of the Service Bulletin AIRBUS INDUSTRIE A330-26-3002.

Ref. : Service Bulletin AIRBUS INDUSTRIE A330-26-3002

EFFECTIVE DATE : MAY 21, 1994

n/C

May 11, 1994

**AIRBUS INDUSTRIE
A330 Aircraft**

94-117-001(B)