

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

**Translation of 'Consigne de Navigabilité' ref. : 94-167-057(B)
In case of any difficulty, reference should be made to the French original issue.**

AIRBUS INDUSTRIE

A320 Aircraft

Sealing of fire wall
(Aircraft equipped with IAE V2500-A1 engines)

This Airworthiness Directive applies to AIRBUS INDUSTRIE A320-231 aircraft, without AIRBUS INDUSTRIE modification 23929 or without AIRBUS INDUSTRIE Service Bulletin A320-78-1009.

In order to prevent, in case of an engine fire, fire propagating through the fire wall caused by incorrect sealing of this fire wall, the following measures are rendered mandatory by this Airworthiness Directive :

- Before April 30, 1995, modify, on each engine, the fire wall in accordance with instructions of AIRBUS INDUSTRIE Service Bulletin A320-78-1009.

No further actions are required after application of either this Airworthiness Directive or AIRBUS INDUSTRIE Service Bulletin A320-78-1009.

Ref. : AIRBUS INDUSTRIE Service Bulletin A320-78-1009
(or any further approved revision)

EFFECTIVE DATE : JULY 30, 1994

n/C

July 20, 1994

**AIRBUS INDUSTRIE
A320 Aircraft**

94-167-057(B)