

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 95-051-058(B)  
In case of any difficulty, reference should be made to the French original issue.

## ATR

### ATR 42 aircraft

Main landing gear side brace pin

This Airworthiness Directive applies to ATR 42 aircraft MSN 121 to 143 including.

In order to prevent the possible rupture of the main landing gear side brace pin further to a defective deshydrogenation after chromium plating, the following measures are rendered mandatory :

- At next scheduled maintenance check or within 6000 landings after the effective date of this Airworthiness Directive, replace the concerned pins in accordance with ATR 42-32-0070 Service Bulletin.

\_\_\_\_\_  
REF. : Service Bulletin ATR 42-32-0070  
\_\_\_\_\_

**EFFECTIVE DATE : MARCH 25, 1995**

v/JPD

March 15, 1995

ATR  
ATR 42 aircraft

95-051-058(B)