

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 1995-127-062(B)
In case of any difficulty, reference should be made to the French original issue.

AEROSPATIALE MATRA ATR

ATR 42 aircraft

Corrosion on wing rear spar (ATA 57)

This Airworthiness Directive applies to ATR 42 aircraft models -200, -300 and -320 the serial number of which is less than 156 and mentioned in paragraph 1-A of Service Bulletin ATR 42-57-0044.

In order to prevent initiation and propagation of corrosion damages on outer wings rear spars, the following measures are rendered mandatory on the effective date of this Airworthiness Directive:

- Before August 31, 1995, inspect the outer wings rear spars and treat the possible damages in accordance with the instructions of Service Bulletin ATR 42-57-0044.

REF. : Service Bulletin ATR 42-57-0044

EFFECTIVE DATE : JULY 01, 1995