

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 95-240-021(B) R1  
In case of any difficulty, reference should be made to the French original issue.

## AIRBUS INDUSTRIE

### A330 Aircraft

Water service door (164 AR)

This Airworthiness Directive applies to AIRBUS INDUSTRIE A330 aircraft models which have not received the modification AIRBUS INDUSTRIE 44130 or 44269 or the associated AIRBUS INDUSTRIE Service Bulletin A330-52-3034.

In order to prevent the opening, or the loss of the water service door (164 AR) due to water valve leakage leading to ice build-up against the door, the following measure is rendered mandatory on the effective date of this Airworthiness Directive :

- Within 500 flight hours, modify the water service door in accordance with the instructions given in AIRBUS INDUSTRIE Service Bulletin A330-52-3034.

Ref. : AIRBUS INDUSTRIE Service Bulletin A330-52-3034  
(or any further approved revisions)

This Revision 1 replaces original issue of this AD.

### EFFECTIVE DATES :

Original AD : DECEMBER 02, 1995  
Revision 1 : AUGUST 09, 1997