

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 95-241-033(B) R2
In case of any difficulty, reference should be made to the French original issue.

AIRBUS INDUSTRIE

A340 Aircraft

Water service door (164 AR)

This Airworthiness Directive applies to AIRBUS INDUSTRIE A340 aircraft -211, -212, -311, -312 and -313 models which have not received the modification AIRBUS INDUSTRIE 44130 or 44269 or the associated AIRBUS INDUSTRIE Service Bulletin A340-52-4042.

In order to prevent the opening, or the loss of the water service door (164 AR) due to water valve leakage leading to ice build-up against the door, the following measure is rendered mandatory on the effective date of this Airworthiness Directive :

- Within 500 flight hours, modify the water service door in accordance with the instructions given in AIRBUS INDUSTRIE Service Bulletin A340-52-4042.

Ref. : AIRBUS INDUSTRIE Service Bulletin A340-52-4042
(or any further approved revisions)

This Revision 2 replaces the AD 95-241-033(B)R1 dated May 07, 1997.

EFFECTIVE DATES :

Original AD : DECEMBER 02, 1995
Revision 1 : MAY 17, 1997
Revision 2 : AUGUST 09, 1997