

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 1996-184-036(B) R2  
In case of any difficulty, reference should be made to the French original issue.

## AIRBUS INDUSTRIE

### A330 Aircraft

Ice protection - Wing anti ice valves (ATA 30)

#### APPLICABILITY :

AIRBUS INDUSTRIE A330 aircraft models -202, -223, -243, -301, -321, -322, -323, -341, -342 which have not received AIRBUS INDUSTRIE modification 46558 nor AIRBUS INDUSTRIE Service Bulletin A330-30-3020.

#### REASON :

To prevent wing anti ice outer valves failures, due to freezing of accumulated water inside the valves mechanism.

This revision 2 takes into account the newly certified A330-323 model.

#### COMPLIANCE :

- The following action is rendered mandatory on the effective date of this Airworthiness Directive at the original issue :
  - Insert into the Aircraft Flight Manual the Temporary Revision (T/R) No. 4.03.00/06 approved by DGAC on July 12, 1996 and apply the corresponding procedure.
- The accomplishment of the AIRBUS INDUSTRIE Service Bulletin A330-30-3020 is a mean of compliance to withdraw the T/R No. 4.03.00/06 dated July 12, 1996 from the Flight Manual and cancels the requirement of this Airworthiness Directive.

Ref. : AIRBUS INDUSTRIE A330 Flight Manual Temporary Revision  
4.03.00/06 approved on July 12, 1996  
(or any further approved revision)  
AIRBUS INDUSTRIE Service Bulletin A330-30-3020  
(or any further approved revision).

This Revision 2 replaces the AD 1996-184-036(B) R1 dated March 10, 1999.

#### EFFECTIVE DATES :

Original AD : SEPTEMBER 21, 1996  
Revision 1 : MARCH 20, 1999  
Revision 2 : JUNE 12, 1999

n/GH

June 02, 1999

AIRBUS INDUSTRIE  
A330 Aircraft

1996-184-036(B) R2