

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 98-071-035(B)
In case of any difficulty, reference should be made to the French original issue.

ATR

ATR 72 aircraft

Engine mount and upper engine fairing stiffener fouling

1/ INVOLVED MATERIAL :

This Airworthiness Directive applies to ATR 72 aircraft models -101, -201, -102, -202, -211, -212 and -212A prior to S/N 540 with the exception of S/N 98, 468, 486, 496, 508, 519 and 523 which are not involved by the present AD.

2/ ACTIONS :

In order to avoid damaging the engine mount, as a consequence of fouling between engine mount and the upper engine fairing stiffener, inspect and if necessary apply the rework instructions in accordance with Service Bulletin ATR 72-54-1011.

3/ COMPLIANCE TIME :

At the first opportunity and at the latest before December 31, 1998.

4/ REFERENCES :

- Service Bulletin ATR 72-54-1011 or its further approved revisions.

EFFECTIVE DATE : FEBRUARY 21, 1998