

CONSIGNE DE NAVIGABILITE

définie par la DIRECTION GENERALE DE L'AVIATION CIVILE

Les examens ou modifications décrits ci-dessous sont impératifs. La non application des exigences contenues dans cette consigne entraîne l'inaptitude au vol de l'aéronef concerné.

DASSAULT AVIATION

Avions FALCON 2000

Capots moteurs

MATERIEL CONCERNE

Avions FALCON 2000, tous numéros de série, n'ayant pas reçu l'application de la modification M1486 ou du Bulletin Service F2000-133.

MOTIF

Afin de pallier le risque de désengagement des crochets de capot moteur lors d'opérations de maintenance, pouvant conduire à la perte de capots en vol, les améliorations de l'installation des capots sont rendues impératives.

ACTION

Dans un délai n'excédant pas 6 mois à partir de la date d'entrée en vigueur de cette consigne, appliquer les dispositions du Bulletin Service DASSAULT AVIATION F2000-133.

REFERENCES

Bulletin Service DASSAULT AVIATION F2000-133 Edition originale ou toute révision ultérieure approuvée.

DATE D'ENTREE EN VIGUEUR : 17 OCTOBRE 1998

Date : 07/10/98

DASSAULT AVIATION
Avions FALCON 2000

98-391-006(B)

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 98-391-006(B)
In case of any difficulty, reference should be made to the French original issue.

DASSAULT AVIATION

FALCON 2000 Aircraft

Engine cowl

APPLICABILITY

FALCON 2000 all serial number, without Modification M1486 or Service Bulletin F2000-133.

REASON

To prevent the risk of Engine cowl hooks disengagement during ground maintenance operations which could result in separation of the engine cowl from the Aircraft, improvements of cowl installation are rendered mandatory.

ACTION

Within a time limit not exceeding six months from the effective date of this Airworthiness Directive, apply dispositions of DASSAULT AVIATION Service Bulletin F2000-133.

REFERENCES

DASSAULT AVIATION Service Bulletin F2000 original issue or any further approved revision.

EFFECTIVE DATE : OCTOBER 17, 1998

n/JYR

October 07, 1998

DASSAULT AVIATION
FALCON 2000 Aircraft

98-391-006(B)