

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 1999-128-060(A) R1
In case of any difficulty, reference should be made to the French original issue.

EUROCOPTER

SA 316/319 helicopters

Limitation of tail rotor blade service life (ATA 05, 64)

1. EFFECTIVITY:

Helicopter models: SE 3160, SA 316B, SA 316C and SA 319B equipped with tail rotor blades
part number: 3160S34.11.000.00
serial numbers: 23484, 23485, 23486, 23487, 23488, 23489, 23490, 23491, 23492, 23493.

2. REASONS:

This AD is issued subsequent to the discovery of a non-compliance of blade cuff stems (blade-to-hub attachment) metallurgical structure affecting the service life of the 10 blades listed above.

Revision 1 of this AD covers the conversion of Service Telex No. 01.66 into Alert Service Bulletin (ASB) No. 01.66 with no change to the technical content.

3. MANDATORY ACTIONS AND COMPLIANCE TIME:

The service life of the blades listed above is limited to 400 hours from the effective date of the original Airworthiness Directive.

REF.: EUROCOPTER Alouette II and Alouette III Alert Service Bulletin No. 01.66.

This Revision 1 replaces AD 1999-128-060(A) dated April 07, 1999.

EFFECTIVE DATES:

Original AD : On receipt of the telegraphic AD
issued on MARCH 25, 1999
Revision 1 : JUNE 23, 2001