# **AIRWORTHINESS DIRECTIVE**

#### released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2000-002-081(A) In case of any difficulty, reference should be made to the French original issue.

#### **EUROCOPTER**

### SA 330 helicopters

Tail rotor blades

## 1. APPLICABILITY

SA 330 helicopters, versions F, G and J fitted with tail rotor blades Part Numbers:

332A-12-0010 all dash numbers 332A-12-0020 all dash numbers.

### 2. REASON

This Airworthiness Directive is issued further to an accident caused by an impact on a tail rotor blade P/N 332A-12-0010 fitted on an AS 332 helicopter.

### 3. MANDATORY ACTIONS AND COMPLIANCE TIME

- **3.1.** Withdraw the blades referenced in paragraph 1 above from service by March 31, 2000 at the latest.
- 3.2. Do not install any of these blades held as spares from March 31, 2000.

REF.: EUROCOPTER SA 330 Service Bulletin No. 01.57

**EFFECTIVE DATE: JANUARY 22, 2000** 

n/DJ

| January 12, 2000 | EUROCOPTER<br>SA 330 helicopters | 2000-002-081(A) |
|------------------|----------------------------------|-----------------|
|------------------|----------------------------------|-----------------|