

M . A . L .

(Mededelingen  
aan nederlandse  
luchtvaardigen  
en eigenaren van  
luchtvaartuigen)

NEDERLAND

RIJKSLUCHTVAARTDIENST  
LUCHTVAARTINLICHTINGDIENST

106/73  
24 Oct

(AIR 801)

PLESMANWEG 1-6, 'S-GRAVENHAGE, TELEFOON 070 - 74 73 27 - 74 73 28 - 74 73 29

**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING**

(BLA)

**NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 (MAL nr. 16/69) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst hierbij de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

*Under authority of the Netherlands Regulations on the State Control of Aviation the Director of the Aeronautical Inspection Directorate of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.*

**73-66-27**

**Fokker F. 27**

- Betreft** : RH aileron trim tab actuator-replacement of setscrew p/n AN565A524H28  
**Subject** : with stud p/n 2045791-1.
- Van toepassing op** : F. 27 Aircraft equipped with  
**Applies to** : AiResearch aileron trim tab actuator (RH) p/n 525458,540604-1 or 540604-2-1.  
This change will be incorporated by AiResearch from actuator serial number -355 and subsequent.
- Tijdstip van uitvoering** : Required before 16th November 1973.  
**Compliance**
- Datum van inwerkingtreding** : October 24, 1973.  
**Effective date**
- Uitvoering** : In accordance with Fokker Service  
**Accomplishment** : Bulletin F-27/27-105 dated 19 October, 1973, or later R.L.D. approved revision.

*All operators of the above-mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.*

Note: Address inquiries regarding this Airworthiness Directive to:  
Civil Aviation Department,  
Aeronautical Inspection Directorate,  
P.O. Box 7555, Telex. 15267, Cable: Civilinspec Schiphol,  
Schiphol Airport - East  
The Netherlands.