

Ministerie van Verkeer en Waterstaat

Rijksluchtvaartdienst

Luchtvaartinspectie (publ. Nr. 79/52)

23 APR

Schiphol-Oost - Gebouw 144 - Stationsplein - Postbus 7555 - Telefoon 020 - 5169111

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING

(BLA)

NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 uitg. 4 (Publ. nr. 79/38) en BLA nr. 74-70-00 uitg. 4 (Publ. nr. 78/101) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.

BLA nr. 77-113-61 Iss. 2

FOKKER F. 27

Betreft: Propellers

Subject: Propeller control system - replacement of unshielded wires by shielded ones and segregation of some wires on a few plugs and receptacles.

Van toepassing op:

Applies to: F.27 Aircraft Serial Numbers:

Part I 10105 to 10248 inclusive (If Fokker service bulletin F27/61-9 (G6) has been incorporated).

10249 to 10518 inclusive (Except aircraft on which Fokker service bulletin F27/61-10 (G7) has been incorporated).

Part II 10519 to 10553 inclusive

This change will be incorporated, prior to delivery, on aircraft serial numbers 10554 and subsequent.

Reason for revision:

To correct the effectivity.

Tijdstip van uitvoering: Required before 31 December, 1978

Compliance:

Datum van inwerkingtreding: 26 April 1979

Effective Date:

Uitvoering: In accordance with Fokker Service Bulletin

Accomplishment: F. 27/61-29 dated 17 October 1977, Revision 2 dated 1 March 1979 or later RLD approved revision.