

Ministerie van Verkeer en Waterstaat

Rijksluchtvaartdienst

Luchtvaartinspectie (publ. Nr. 78/78)

30 MAY

Schiphol-Oost - Gebouw 144 - Stationsplein - Postbus 7555 - Telefoon 020 - 5169111

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING

(BLA)

NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 uitg. 3 (publ. nr. A110/77) en BLA nr. 74-70-00 uitg. 3 (MAL nr. 35/76) maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.

BLA nr. 78-57-30

FOKKER F. 27

Betreft: ICE AND RAIN PROTECTION

Subject: General - protection of cable loom and if necessary relocation of de-icing relay panel.

Van toepassing op:

Applies to: F27 Aircraft Serial Numbers:

10299 to 10547 inclusive.

On aircraft serial numbers 10548 and subsequent the rear de-icing relay panel will have a relocated position.

Tijdstip van uitvoering:

Compliance: Required before 1 August 1978.

Datum van inwerkingtreding: 1 June 1978

Effective Date:

Uitvoering:

Accomplishment:

In accordance with Fokker Service Bulletin F. 27/30-34 dated 17 April 1978 or later RLD approved revision.

All operators of the above mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:

Civil Aviation Department

Aeronautical Inspection Directorate

P.O. Box 7555

1117 ZH SCHIPHOL

The Netherlands

Telex: 15267 rldli nl

Telef: 020 - 51632 79