

Ministerie van Verkeer en Waterstaat
Rijksluchtvaartdienst
Luchtvaartinspectie

BLA

(publ. Nr. 80/10)

25 JAN.

Schiphol-Oost - Gebouw 144 - Stationsplein - Telefoon 020 - 5169111

BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE

Onder verwijzing naar BLA nr. 68-19-00 uitg. 4 en BLA nr. 74-70-00 uitg. 5 maakt de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing bekend.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department prescribes hereby the following Airworthiness Directive.

BLA nr. 80-08-27

FOKKER F. 28

Betreft: Wing flap mechanical actuators-repetitive
Subject: inspection for wear of ball return tube in ball nut.
Van toepassing op: F28 Aircraft as far as equipped with one or
Applies to: more flap actuators in post Menasco Service Bulletin 27-63 or 27-66 configuration.

Tijdstip van uitvoering: -At the next check A.
Compliance: -Subsequently at every 500 flights.

Datum van inwerkingtreding: 30 January 1980
Effective date:

Uitvoering: In accordance with Fokker Service Bulletin
Accomplishment: F.28/27-137 dated 28 January 1980
or later RLD approved revision.

All operators of the above mentioned aircraft are receiving this Service Bulletin directly from the aircraft manufacturer.

Note: Address inquiries regarding this Airworthiness Directive to:
Civil Aviation Department
Aeronautical Inspection Directorate
P.O. Box 7555
1117 ZH Schiphol
The Netherlands
Telex: 15267 rldli nl
Telef: 020 - 51632 80