



**BIJZONDERE LUCHTWAARDIGHEIDSAANWIJZING
(BLA)
NETHERLANDS AIRWORTHINESS DIRECTIVE**

Onder verwijzing naar BLA nr. 68-19-00 en BLA nr. 74-70-00 geeft de directeur Luchtvaartinspectie van de Rijksluchtvaartdienst de volgende Bijzondere Luchtwaardigheidsaanwijzing.

Under authority of the Netherlands Regulations on the State Control of Aviation the Director Aeronautical Inspection of the Civil Aviation Department gives the following Airworthiness Directive.

NACELLES / PYLONS - HINGED FAIRING FOLDING STRUT - REPLACEMENT

Description:

To prevent automatically locking of the folding strut and subsequent damage to the hinged fairing on top of the engine nacelle, the folding strut must be replaced by a new type which has a manually operated lock.

Effectivity:

F.27 Mk. 050 aircraft serial numbers:

20103 to 20108 inclusive, and 20110 to 20122 inclusive.

Effective date: June 17, 1988

Compliance: required before July 01, 1988

Accomplishment: In accordance with Fokker Service Bulletin F50-54-002 dated June 17, 1988 or a later RLD-approved revision.

Remarks:

- 1) In respect to art.88 par.3 of the State Control of Aviation Act, this Airworthiness Directive (BLA) has to be accomplished by or under supervision of an approved company.
- 2) All operators of the affected aircraft are receiving the ref. Service Bulletin directly from the manufacturer.

Note:

Address inquiries regarding this AD to:

Civil Aviation Department
Aeronautical Inspection Directorate
P.O.Box 7555, 1117 ZH Schiphol Airport, The Netherlands
Telex: 15267 rldli nl, Telephone: ()-31-(0)20-516 32 78

ISSN 0920 - 1084