

DCA/R2000/38 Cabin Compartment Barrier – Inspection and Modification

Applicability: Model HR 200/100, HR 200/100S, HR 200/120, HR 200/120B and HR 200/160 aircraft, S/Ns 001 through 378.

Model R 2100, R 2100 A, R 2112, R 2120 U, R 2160, R 2160 D and R 2160 I aircraft, S/Ns 001 through 378.

Requirement: To ensure that the aircraft is in compliance with FAR 23.967(d) inspect the aircraft to determine if a metal barrier is installed behind the seats, per Alpha Aviation Service Bulletin No. AA-SB-28-001.

If a metal barrier is installed per SB No. AA-SB-28-001, then no further action is required.

If a metal barrier is not installed, manufacture and install a barrier per SB No. AA-SB-28-001 and Alpha Aviation Drawing No. 60-53-119. (Alpha Aviation SB AA-SB-28-001 refers)

Note: For a copy Alpha Aviation Service Bulletin AA-SB-28-001 contact:

Alpha Aviation Ltd
Ingram Road
Hamilton Airport RD 2
Hamilton 2021
New Zealand
Phone: 0064 7 843 7070
Fax: 0064 7 843 8040
Web: www.alphaaviation.co.nz

Compliance: Within the next 100 hours TIS or by 29 June 2007, whichever occurs sooner.

Effective Date: 29 June 2006