

Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE No: 1-056

AIRCRAFT TYPE: SAAB 340B

SERIAL No:s

AFFECTED: SAAB 340B-271 and -275 through -300.

SUBJECT: Replacement of actuator on motor operated fuel valves to meet EMI requirements.

BACKGROUND: To fully meet Electromagnetic Interference (EMI) requirements the existing actuator assembly on fuel valves installed on affected aircraft must be replaced with a new actuator.

REFERENCE

DOCUMENTS: Saab Aircraft AB Service Bulletin SAAB 340-28-016 dated 21 October, 1992.

ACTIONS: Convert valve assembly P/N AV16B2117B-2 to P/N AV16B2117B-4B as described in Saab Aircraft AB Service Bulletin SAAB 340-28-016 dated 21 October, 1992 or later revision.

COMPLIANCE

TIME: To be accomplished no later than 1 April, 1993.

EFFECTIVE

DATE: 22 October, 1992

LUFTFARTSVERKET
Flight Safety Department

LFS: 1992:35

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.