

SWEDISH AIRWORTHINESS DIRECTIVES (SAD)

SAD No 1-098
Cancels
SAD No 1-097

Section 1. Swedish Manufactured Aeronautical Products

AIRWORTHINESS

DIRECTIVE No: 1-098

AIRCRAFT TYPE: SAAB 2000

SERIAL No:s

AFFECTED: SAAB 2000-005 through -036

SUBJECT: Lights - Ceiling/Window and Lavatory Lights - Inspection, Rework and Replacement of the Fluorescent Light Lamp-Holders

BACKGROUND: A number of instances of damage to the lampholders of the ceiling/window fluorescent lights have been reported. The damage is melting, charring and in two instances, smoke emission from the lampholders. There are two types of lampholders installed. They are; BRUCE INDUSTRIES Part No. BVO3300 and PAGE AEROSPACE Part No. C756-10-001. The reported incidents were of damage to the PAGE Part No. C756-10-001 lampholders. To avoid more incidents it is necessary to identify and repair or replace faulty lampholders.

REFERENCE

DOCUMENTS: Saab Aircraft AB Service Bulletin SAAB 2000-33-009, dated 19 June, 1996 or later revision.

ACTIONS: Perform actions described in Saab Aircraft AB Service Bulletin SAAB 2000-33-009, dated 19 June, 1996, or later revision.

COMPLIANCE

TIME: To be performed within 2 month after the effective date of this SAD.

EFFECTIVE

DATE: 19 June, 1996

LUFTFARTSVERKET
Flight Safety Department

LFS 1996:42

The actions contained in this directive and reference document(s) have been classified as mandatory for aircraft on Swedish register.