



EASA Safety Information Bulletin

SIB No.: 2010-36
Issued: 09 December 2010

- Subject:** Embraer EMB-505 aeroplanes - Terrain Awareness Warning System (TAWS)
- Ref. Publication:** Federal Aviation Administration (FAA) Special Airworthiness Information Bulletin (SAIB) [CE-10-46](#) dated 16 August 2010.
- Applicability:** Embraer EMB-505 aeroplanes, all serial numbers.
- Description:** The FAA have published the referenced advisory document to advise operators and owners of Embraer EMB-505 aeroplanes of an airworthiness concern that the terrain awareness warning system (TAWS) information in the original airplane flight manual (AFM) is insufficient to meet the relevant certification requirements.
- After reviewing the available information and recognising that the FAA is not the 'State of Design' authority for this type design, EASA concurs with the advisory.
- This SIB is published to ensure that all owners and operators of the affected aeroplanes, registered in European Union Member States or associated countries, are aware of these recommendations.
- Recommendation:** EASA recommends that owners and operators use Embraer AFM-2666, Revision 1. This revision should be available to owners and operators through the Type Certificate holder's website and service organization.
- Contacts:** For further information contact the Airworthiness Directives, Safety Management & Research Section, Certification Directorate, EASA. E-mail: ADs@easa.europa.eu.
- For copies of the referenced AFM revision, contact [Embraer](#), Av. Brigadeiro Faria Lima, 2.170, 12227-901, São José dos Campos, SP, Brazil.