EASA SIB No: 2013-09



## **EASA Safety Information Bulletin**

SIB No.: 2013-09 Issued: 10 July 2013

Subject: Notification of Suspected Unauthorised Overhaul / Repair of

Fixed-Pitch Propellers and/or Blades

**Ref. Publication:** Hoffmann Propeller Service Bulletin No. <u>61-00-03 E27A</u>,

dated 28 June 2013.

**Applicability:** All Hoffmann fixed-pitch propellers.

These propellers are known to be installed on, but not limited to, powered sailplanes and small aeroplanes, certificated

under CS22, CS23, CS-VLA or CS-LSA.

**Description:** Hoffman Propeller has informed EASA about reported

occurrences of unauthorized overhaul/repair of fixed-pitch propellers. These propellers are suspected to have been overhauled/repaired without authorisation from Hoffmann, and consequently, work may have been carried out without using approved procedures. Such actions could seriously

affected the safe operation of the propeller.

At this time, the safety concern described in this SIB is not considered to be an unsafe condition that would warrant Airworthiness Directive (AD) action under EU 748/2012, Part

21.A.3B.

**Recommendation(s):** Owners, operators and maintenance organizations are

encouraged to review the records of fixed-pitch propellers and blades to determine whether maintenance or repair has been

accomplished by an unauthorized organisation.

A propeller or blade that is found to have been overhauled or repaired by an unauthorized organisation must be considered unapproved and not eligible for installation on an aeroplane.

EASA recommends to remove each affected propeller and/or blade from service and under quarantine, until the affected propeller/blade can be restored to an airworthy condition.

This is information only. Recommendations are not mandatory.

EASA SIB No: 2013-09

## Contact(s):

For further information contact the Safety Information Section, Executive Directorate, EASA. E-mail: <a href="mailto:ADs@easa.europa.eu">ADs@easa.europa.eu</a>.

For instructions on how to restore an affected propeller to an airworthy condition, contact Hoffmann Propeller GmbH & Co. KG, Küpferlingstrasse 9, 83022 Rosenheim, Germany, Telephone +49 (0)8031-1878-0, Fax +49 (0)8031-1878-78,

E-Mail: <a href="mailto:info@hoffmann-prop.com">info@hoffmann-prop.com</a>
Internet: <a href="mailto:www.hoffmann-prop.com">www.hoffmann-prop.com</a>