| | All | RWORTHINESS DIRECTIVE | Distributio | n: | Issue date: | Page : |
|---|---|-----------------------|--------------------------------------|----|---|--------|
| | No F-2004-089 | | Α | | June 23, 2004 | 1/2 |
| Direction générale de l'aviation civile France | This Airworthiness Directive is published by the DGAC: X on behalf of EASA, the Primary Airworthiness Authority for the affected product. as the Registration Airworthiness Authority for the affected aircraft | | | ne | Translation of « Consigne de Navigabilité » of same number. In case of difficulty, reference should be made to the French issue. | |
| GSAC publication | No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive, unless otherwise agreed with the Authority of the State of Registry. | | | | | |
| Corresponding foreign Airworthiness Directive(s): Air | | | sirworthiness Directive(s) replaced: | | | |
| Not applicable | | | None | | | |
| = | | | Type(s): AS 350 helicopters | | | |
| Type certificate(s) No. 84 | | | | | | |
| TCDS No 157 | | | | | | |
| ATA chapter: | | Subject: | | | | |
| 29 | Hydraulic system - Hydraulic cut off function | | | | | |

1. **EFFECTIVITY**:

AS 350 helicopter versions B, B1, B2, B3, BA, BB and D, pre-MOD 073263.

2. REASON:

The aim of this Airworthiness Directive (AD) is to eliminate the possibility of a load unbalance in the flight controls, due to residual pressure in the system, after cutting off the hydraulic assistance, following a hydraulic failure, in particular in low outside temperature conditions.

3. MANDATORY ACTION AND COMPLIANCE TIME:

The following measure is rendered mandatory from the effective date of this AD:

- At the latest by December 31, 2004, embody the modifications to the electrical wiring, in compliance with the instructions specified in § 2.A., 2.B. and 2.C. of referenced EUROCOPTER AS 350 Alert Service Bulletin No. 29.00.07.

4. REFERENCE PUBLICATION:

EUROCOPTER AS 350 Alert Service Bulletin No. 29.00.07 (Any subsequent approved revision to this ASB is acceptable).

5. **EFFECTIVE DATE**:

July 03, 2004.



AIRWORTHINESS DIRECTIVE No F-2004-089

Distribution:

Α

Issue date:

June 23, 2004

Page: **2/2**

6. REMARK:

For any questions concerning the technical content of the requirements in this AD, please contact:

EUROCOPTER (STXI) - Aéroport de Marseille Provence, 13725 Marignane Cedex - France

Phone: +33 (0)4 42 85 97 97 – Fax: +33 (0)4 42 85 99 66 E-mail: Directive.technical-support@eurocopter.com

7. APPROVAL:

This AD is approved under EASA reference No 2004-6365 dated June 15, 2004.