


<b>EASA</b>	<b>AIRWORTHINESS DIRECTIVE</b>	
	<b>AD No: 2006 - 0170</b>  <b>Date: 19 June 2006</b>	
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.		
<b>Type Approval Holder's Name:</b>		<b>Type/Model designation(s):</b>
Brantly International, Inc.		Brantly (Hynes) Series Helicopters
TCDS Number: FAA 2H2 Rev. 23		
Foreign AD: None		
Supersedure: UKCAA Additional Airworthiness Directives 0467 PRE 78		
<b>ATA 05</b>	<b>Time Limits - Replacement</b>	
<b>Manufacturer(s):</b>	Brantly International Inc.	
<b>Applicability:</b>	All Brantly series helicopters fitted with tail rotor blades Part No. B2-111-11.	
<b>Reason:</b>	A National Aviation Authority, prior to the formation of EASA, has determined that a Mandatory Replacement Life for the tail rotor blade Part No. B2-111-11 is necessary to maintain an acceptable level of safety. EASA concurs with this position.	
<b>Effective Date:</b>	03 July 2006.	
<b>Compliance:</b>	Compliance with this Directive requires that the tail rotor blades, Part No. B2-111-11, are subject to a Mandatory Replacement Life of 1,500 hours.  This Directive does not apply to tail rotor blades Part No. B2-111-11A.	
<b>Ref. Publications:</b>	None	
<b>Remarks:</b>	<ol style="list-style-type: none"> <li>1. If requested and appropriately substantiated the responsible EASA manager for the related product has the authority to accept Alternative Methods of Compliance (AMOCs) for this AD.</li> <li>2. This AD was posted as PAD 06-100 for consultation on 19 April 2006 with a comment period until 15 May 2006. The Comment Response Document can be found at <a href="http://ad.easa.eu.int/">http://ad.easa.eu.int/</a>.</li> <li>3. Enquiries regarding this Airworthiness Directive should be referred to Mr. M. Capaccio, Airworthiness Directive Focal Point - Certification Directorate, EASA.</li> </ol>	

E-mail: [ADs@easa.eu.int](mailto:ADs@easa.eu.int)

4. For questions concerning the technical contents of this AD requirements, contact Brantly International Inc. Wilbarger County Airport, 12399 Airport Drive, Vernon, Texas 76384