

Bi-Weekly Report of EASA published ADs between 26/03/2007 - 08/04/2007

easa.europa.eu

| AD Number | Status | Approval's Date | TC-Holder | Type/Model | Subject |
|-------------|---------------|--------------------|--|---|--|
| 2007-0090-E | Supersedure | 05/04/2007 | Eurocopter | AS 332 L2 and EC 225 LP helicopters | Fuselage – Intermediate Gearbox (IGB) Fairing Gutter – Check/Reconditioning |
| 2007-0089 | Initial Issue | 04/04/2007 | Agusta S.p.A | AB 206 series | Main Rotor Drive – Transmission Pylon Support Spindle – Identification/Replacement |
| 2007-0088-E | Initial Issue | 30/03/2007 | Piaggio Aero Industries SpA | P.180 'Avanti' series | Steering system components & Hydraulic fluid - Inspection / Replacement |
| 2007-0087 | Initial Issue | 30/03/2007 | BAE Systems (Operations) Limited | HP 137 Jetstream MK 1, Jetstream Series 200, 3100 and 3200 | Landing Gear – Main Landing Gear (MLG) Radius Rod – Inspection / Replacement |
| 2007-0086 | Supersedure | 30/03/2007 | Rolls-Royce Deutschland Ltd. & Co. KG. | Tay 650-15, Tay 651-54 | Engine - High Pressure Turbine - Reduction of Declared Safe Cyclic Lives |
| 2007-0085 | Initial Issue | 30/03/2007 | Turbomeca | ARRIEL 2B1 Turboshaft engines | Engine Fuel & Control - Engine Electronic Control Unit (EECU) - Modification |
| 2007-0084 | Initial Issue | 30/03/2007 | Turbomeca | Turbo-shaft engine MAKILA 2A | Change to Civil Use Following Use by an Operator Not Controlled by a Civil Authority |
| 2007-0083-E | Supersedure | 29/03/2007 | Eurocopter | EC 225 LP helicopters | Rotor(s) - Main Rotor Hub Coning Stop Support Attachments to Dome Fairing - Check / Readjustment |
| 2007-0082-E | Initial Issue | 27/03/2007 | Eurocopter | AS 332 and SA 330 helicopters | Engine Controls - Fuel Shut-Off Control Lever - Check / Reconditioning |
| 2007-0081 | Supersedure | 26/03/2007 | Airbus | A340-500/-600 Series | Auxiliary Power Unit (APU) – APU and APU Generator Interference - Inspection / Modification |
| 2007-0080-E | Initial Issue | 26/03/2007 | Airbus | A330 and A340 aircraft | Electrical Power/Auxiliary Power Unit - Oil Pump Module -Inspection |
| 2007-0079 | Initial Issue | 26/03/2007 | Eurocopter | AS 332 L2 | Fuselage - Cracks on Frame 5295-Inspection/Modification/Repair |