



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|------------------------------|---|--|
| 2009-0276 | 2009-12-23 | ATR | ATR42, ATR72 | Fire Protection - Halon 1211 Fire Extinguishers - Identification / Replacement |
| 2009-0279 | 2009-12-23 | GROB | G115 | Canopy - Jettison Test / Repair |
| 2009-0277 | 2009-12-23 | EUROCOPTER | AS 350, AS 355, EC 120, EC 130, SA 341, SA 342J | Fire Protection - Portable Halon 1211 Fire Extinguishers - Identification / Replacement |
| 2009-0278 | 2009-12-22 | SICLI | H1-10 AIR Portable Fire Extinguisher | Fire Protection - Portable Halon 1211 Fire Extinguishers - Identification / Replacement |
| US-2009-24-06 | 2009-12-22 | GENERAL ELECTRIC | CF34 | EASA DECISION NOT TO ADOPT FAA AD 2009-24-06 - SEE ANAC BRAZIL AD 2008-03-01R2 |
| 2009-0271 | 2009-12-21 | EUROCOPTER | AS 332, SA 330 | Equipment & Furnishings - Hydraulic Hoist Cable - Limitation / Modification |
| 2009-0275-E | 2009-12-21 | EUROCOPTER | AS 332, EC225 | Fuselage - Intermediate Gear Box (IGB) Fairing Gutter - Inspection / Replacement |
| 2009-0273-E | 2009-12-21 | ROLLS-ROYCE DEUTSCHLAND | BR700-715 | Engine - High Pressure Compressor/Front Drum Assembly - Reduced Life Limit/Replacement |
| 2009-0217-E | 2009-12-21 | SIKORSKY | S92 | CANCELLATION NOTICE - EASA HAS ADOPTED FAA AD 2009-25-10 |
| 2009-0274-E | 2009-12-18 | AGUSTA | A109 | Main Rotor - Fixing Bolts of the Scissor Fitting Assembly - Inspection/Replacement |
| 2009-0272 | 2009-12-18 | EUROCOPTER DEUTSCHLAND | EC 135, EC 635 | Main Rotor - Sliding Sleeve - Pre-Flight Check Amendment |
| 2009-0242 | 2009-12-18 | ATR | ATR42, ATR72 | Time Limits / Maintenance Checks - Certification Maintenance Requirements and Critical Design Configuration Control Limitations [Fuel Tank Safety] |
| 2009-0261-E | 2009-12-18 | TURBOMECA | TURMO IVA, IVC | Intermediate Bearing Return Flexible Pipe Unions - Inspection / Replacement |
| 2009-0266 | 2009-12-17 | 328 Support Services GmbH | 328-100, 328-300 | Flight Controls - Aileron Trim- and Rudder Spring Tab Fittings - Replacement |
| 2009-0270 | 2009-12-17 | CFM INTERNATIONAL | CFM56-5, CFM56-5B, CFM56-7B | Engine - LPT Rotor / Stator Assembly - Replacement |
| 2007-0053R3 | 2009-12-17 | AIRBUS | A310 | Fuselage / Stabilisers / Wings - Structural Fatigue - Inspection / Modification |
| 2009-0267 | 2009-12-17 | BAE SYSTEMS (OPERATIONS) LTD | JETSTREAM3100, JETSTREAM3200 | Flight Controls - Flap Selector Switch Wiring - Modification |
| CF-2009-50 | 2009-12-17 | BOMBARDIER | CL600 2B16 | Air-Driven Generator (ADG) - Non-Conforming Balance Washer Screws |



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|-------------------------------|--|--|
| 2009-0269 | 2009-12-17 | FOKKER SERVICES | F28 | Landing Gear - Main Landing Gear (MLG) - Modification / Replacement |
| 2009-0268 | 2009-12-17 | FOKKER SERVICES | F28 | Landing Gear - Main Landing Gear (MLG) Upper Side Brace Assembly - Modification / Replacement |
| CF-2009-49 | 2009-12-17 | BOMBARDIER | CL600 2A12, CL600 2B16 | Wing Leading Edge Thermal Switches and Wing Anti-Ice Duct Piccolo Tubes - Airworthiness Limitation Tasks |
| 2009-0265 | 2009-12-16 | AIRBUS | A380 | Pneumatic - Overheat Detection System - Inspection |
| US-2009-26-01 | 2009-12-16 | CIRRUS | SR22 | Ice and Rain Protection - Inspection |
| 2009-0263 | 2009-12-16 | EUROCOPTER | AS 332, EC225 | Equipment & Furnishings - Emergency Flotation Gear - Inspection / Repair / Replacement |
| 2009-0264 | 2009-12-15 | AGUSTA | A109 | Electrical Power - Battery Bus (BATT BUS) Circuit Breaker - Modification |
| US-2009-21-07 | 2009-12-15 | GENERAL ELECTRIC | CF6 | [Correction] Thrust Reverser Ballscrew Gearbox Assembly Adjustable-length End Actuators - Inspection / Replacement |
| 2009-0262 | 2009-12-15 | FIRE FIGHTING ENTERPRISES LTD | Halon 1211 (BCF) Fire Extinguishers | Fire Protection - Halon 1211 Fire Extinguishers - Identification / Replacement |
| CF-2009-46 | 2009-12-14 | BOMBARDIER | DHC-8 | Landing Gear Alternate Extension Access Panel - Potential Failure to Open |
| 2009-0260 | 2009-12-14 | AIRBUS | A330, A340 | [Correction] Hydraulic Power - Ram Air Turbine (RAT) Balance Weight Screws - Inspection / Replacement |
| CF-2009-48 | 2009-12-14 | BOMBARDIER | CL600 2B19, CL600 2C10, CL600 2D15, CL600 2D24 | Air-Driven Generator (ADG) - Non-Conforming Balance Washer Screws |
| CF-2009-44 | 2009-12-14 | HONEYWELL ASCa | ELT | Emergency Locator Transmitter - Potential Failure To Transmit The Required 406MHz Coded Signal |
| US-2009-25-11 | 2009-12-14 | BOEING | 747 | Fuselage - Lower Lobe Body Frames - Inspection / Modification |
| CF-2009-47 | 2009-12-14 | BOMBARDIER | CL600 2B19, CL600 2C10, CL600 2D15, CL600 2D24 | Air-Driven Generator Electrical Harness Assembly - Potential Failure Due To Corrosion |