



Publ. number	Issue Date	TC Holder	Type	Subject
2011-0111	2011-06-10	EUROCOPTER DEUTSCHLAND	EC 135	Air Conditioning - Mechanical Air Conditioning System - Inspection / Deactivation
CF-2011-12	2011-06-09	BOMBARDIER	DHC-8	Cracked Rudder Actuator Mounting Bracket
2011-0109	2011-06-08	SIKORSKY	S92	Main Rotor Drive - Main Gearbox (MGB) Assembly - Inspection / Replacement
CF-2011-11	2011-06-08	BOMBARDIER	CL-600 (Challenger)	Oxygen Supply System - Deformation of the Pressure Regulator on the Oxygen Cylinder and Regulator Assembly and installation of protection on the Electrical Wiring Harness
2011-0108	2011-06-07	EUROCOPTER	EC 155	Fuselage - Upper Fin / Fenestron Attachment Fittings - Inspection / Replacement
2011-0107	2011-06-07	EUROCOPTER DEUTSCHLAND	BK 117	Doors - Sliding Door Emergency Jettison System - Inspection
2010-0204	2011-06-07	ROCKWELL COLLINS	TDR-94 Transponders, TDR-94D Transponders	[Correction] Navigation Systems - Mode-S Transponder - Modification / Replacement
2011-11-05	2011-06-06	BOEING	DC-10, MD-10, MD-11	Fuel Pump Housing Electrical Connector Assembly. Replacement. Repetitive inspections and Corrective Actions.
2011-0098	2011-06-02	AIRBUS, BOEING, FOKKER SERVICES	A300-600, A310, A318, A319, A320, A321, A330, A340, 717, 737, 747, 757, 767, 777, DC-9, MD-11, MD-88, MD-90, F27	Equipment & Furnishings - Passenger Seat - Replacement
BR-2011-05-05	2011-05-31	EMBRAER	EMB505	Replacement of attaching bolts of balance mass weights to elevators.
2011-0105	2011-05-31	EUROCOPTER	AS 365, EC 155, SA 365, SA 366	Time Limits and Maintenance Checks - Tail Gearbox (TGB) Oil Level and Magnetic Chip Detector - Inspection Tail Rotor - Pitch Control Rod Bearing - Inspection / Replacement
2011-0106	2011-05-31	TECNAM	P2002	Fuel - Fuel Hoses - Inspection
2011-0085	2011-05-31	AIRBUS	A300-600, A310	[Correction] Doors - Forward Cargo Door High Pressure Pipe - Replacement
US-2011-08-51	2011-05-31	BOEING	737	[Final Rule] Fuselage - Fuselage Lap Joint at Stringers S-4R and S-4L - Inspection / Repair
2011-0058R1	2011-05-31	AIRBUS	A380	[Correction] Pneumatic - Pylon Bleed Duct - Inspection / Replacement