



| Publ. number  | Issue Date | TC Holder  | Type   | Subject  |
|---------------|------------|--|--|--|
| 2013-0276     | 2013-11-21 | DOWTY<br>PROPELLERS  | R184/4-30-4/50,<br>R193/4-30-4/50,<br>R193/4-30-4/61,<br>R193/4-30-4/63,<br>R193/4-30-4/64,<br>R193/4-30-4/65,<br>R193/4-30-4/66,<br>R201/4-30-4/20,<br>R212/4-30-4/22,<br>R251/4-30-4/49,<br>R257/4-30-4/60 | Propellers - Blade Bearing Preload - Inspection  |
| CF-2013-36    | 2013-11-21 | BOMBARDIER   | DHC-8  | Auto-Ignition System - Incorrect Wire Installation   |
| 2013-0229R1   | 2013-11-21 | ROLLS-<br>ROYCE<br>DEUTSCHLAN<br>D   | BR700-710  | Engine Fuel and Control - Fuel Metering Unit - Replacement   |
| 2013-0275     | 2013-11-20 | AGUSTAWES<br>TLAND, BELL<br>HELICOPTER<br>TEXTRON<br>CANADA<br>(BHTC), BELL<br>HELICOPTER<br>TEXTRON<br>Inc. (BHTI),<br>EUROCOPTER,<br>EUROCOPTER<br>R,<br>EUROCOPTER<br>R<br>DEUTSCHLAN<br>D, MD<br>HELICOPTER<br>S INC (MDHI),<br>SIKORSKY | AB 139, AB 412,<br>AW 139,<br>AW109SP, 429,<br>430, 212, 214,<br>214ST, 412, AS<br>332, AS 365,<br>EC225, BK 117,<br>EC 135, EC 635,<br>MD900, S-61, S-<br>76, S-92  | Equipment / Furnishing - Hoist - Test / Replacement  |
| US-2013-20-18 | 2013-11-19 | BELL<br>HELICOPTER<br>TEXTRON<br>Inc. (BHTI)   | 412  | Main Rotor Yoke - Life Limit / Reidentification  |
| US-2013-23-03 | 2013-11-19 | BOEING   | 747  | Wings - Outboard Flap Inboard Actuator Attach Fittings - Inspection / Replacement                            |
| US-2013-23-04 | 2013-11-19 | BOEING   | 737  | Fuselage - Titanium Seat Track Bolts - Replacement / Splice Strap and Forward Seat Track Holes - Inspections |



| Publ. number  | Issue Date | TC Holder   | Type                              | Subject   |
|---------------|------------|---|-----------------------------------|---|
| 2013-0273-E   | 2013-11-15 | HOFFMANN  | HO-V352                           | Propellers - Locknuts - Identification / Replacement                                      |
| US-2013-22-06 | 2013-11-15 | BOEING  | 747                               | Fuselage - Upper Deck Tension Ties - Inspection / Repair / Modification                   |
| 2013-0274     | 2013-11-15 | AIRBUS  | A330, A340                        | Hydraulic Power - Ram Air Turbine Hydraulic Pumps - Identification / Replacement          |
| CF-2013-33R1  | 2013-11-15 | PRATT &<br>WHITNEY<br>CANADA  | PT6A-100, PT6A-<br>20, PT6A-30    | Power Turbine Containment Ring Failure  |
| US-2013-22-11 | 2013-11-15 | BOEING  | 747                               | Fuselage - Sections 41 & 44 Upper Deck Floor Beam Upper Chords - Inspection / Repair      |
| 2013-0272     | 2013-11-14 | AIRBUS  | A340                              | Wings - Centre Wing Box / Keel Beam Fastener Hole at Frame 40 - Inspection / Modification |
| 2013-0271     | 2013-11-14 | AIRBUS  | A330, A340                        | Wings - Main Landing Gear Rib 6 Aft Bearing Lugs - Inspection / Replacement               |
| 2013-0270     | 2013-11-14 | AIRBUS  | A330, A340                        | Stabilizers - Rudder Side Panel Along the Z-Profile - Inspection                          |
| US-2013-22-21 | 2013-11-11 | APICAL<br>INDUSTRIES<br>INC., BELL<br>HELICOPTER<br>TEXTRON<br>CANADA<br>(BHTC) | Emergency Float<br>Kits, 206, 407 | Emergency Float Kit - Float Inflation Hoses - Inspection / Labeling / Replacement         |