



Publ. number	Issue Date	TC Holder	Type	Subject
2016-0238	2016-12-02	AIRBUS	A318, A319, A320, A321	Fuselage - Door Stop Fitting Holes at Frames 66/68 - Inspection / Repair
2016-0239	2016-12-02	AIRBUS	A318, A319, A320, A321	Time Limits / Maintenance Checks - Airworthiness Limitation Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Implementation
2016-0240	2016-12-02	AIRBUS HELICOPTERS	AS 350 / EC 130	Fuselage - Tail Boom / Fenestron Junction Frame - Inspection
2015-0210R2	2016-12-02	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Hydraulic Power - Plate Assembly Attachment Points - Inspection / Check
2016-0237-E	2016-12-01	MECAER AVIATION GROUP SpA	NH-500D	Main Rotor - Blades - Inspection / Replacement
US-2016-24-02	2016-11-29	BOEING	747	Wings - Flap Track Aluminium Transmission Aft Bearing Plate Assemblies - Replacement
CF-2016-36	2016-11-29	BOMBARDIER	DHC-8	Landing Gear - Main Landing Gear Retraction Actuator Rod-End Failure
2016-0003R1	2016-11-29	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Engine Fuel & Control - Main Injector Half-Manifolds and Preference Injector - Replacement
2016-0236	2016-11-25	AIRBUS	A340	Exhaust - Thrust Reverser - Replacement [Life Limit]
2016-0235	2016-11-24	SAFRAN HELICOPTER ENGINES	ARRIEL 2	Engine - Front Support - Replacement
2016-0234	2016-11-24	SAAB AB, AERONAUTICS	340	Lights - Passenger Reading Light / Circuit Breaker - Replacement
2016-0156R1	2016-11-23	DIAMOND AIRCRAFT INDUSTRIES	DA 42 / 62	Engine Exhaust - Exhaust Pipes - Replacement
CF-2016-35	2016-11-23	BOMBARDIER	CL-600 (Regional Jet)	Pneumatic - Failure of High Pressure Bleed Air Duct Shrouds
US-2016-22-07	2016-11-23	BELL HELICOPTER TEXTRON Inc. (BHTI)	204B, 205	Main Rotor - Blades - Inspection / Repair / Replacement
2016-0233	2016-11-23	AEROCLUBUL ROMANIEI	IS-28	Fuselage - Aft Fuselage Frames and Stringers - Inspection
2016-0232	2016-11-22	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Rotor Drive(s) - Main Gear Box / Emergency Spraying System - Modification / Functional Test
2016-0231	2016-11-22	AIRBUS	A330, A340	Wings - Inboard Flap Parts - Identification / Inspection
CF-2015-01R1	2016-11-22	PRATT & WHITNEY CANADA	PT6B	Engine Indicating - Incorrect Engine Torque Indication
US-2016-24-51	2016-11-21	SIKORSKY	S-92	Tail Rotor Pitch Change Shaft - Inspection
2016-0230	2016-11-21	DASSAULT AVIATION	Falcon 7X	Standard Practices Airframe - Electrical Wiring - Inspection / Modification