



Publ. number	Issue Date	TC Holder	Type	Subject
BR-2020-01-01	2020-01-10	EMBRAER	EMB-505 (Phenom 300)	Stabilizers - Control Surface Mass-balance Weights and Attachments - Inspection / Replacement
2020-0003	2020-01-09	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 900	Engine Fuel & Control - Hydro-mechanical Metering Units - Removal from Service
2020-0004	2020-01-09	AIRBUS HELICOPTERS	EC175	Fuselage - Lower Fuselage Fuel Tank Structure and Equipment Electrical Connectors - Rework / Relocation
2020-0001	2020-01-08	CEAPR	DR 400	Air - Air Intake Duct - Modification / Inspection
US-2019-25-14	2020-01-08	BOEING	777	Stringer Splices and Skin Splice Straps - Repetitive Inspections
US-2019-25-12	2020-01-08	BOEING	777	Oxygen - Low-Pressure Oxygen Flex Hoses - Replacement
2020-0002	2020-01-08	FOKKER SERVICES	F28	Fuselage - Frame Inboard Boom - Inspection
US-2019-22-09	2020-01-07	BOEING	787	Fuselage - Main Landing Gear Aft Hanger Link Lug Fittings - Inspection
US-2019-23-12	2020-01-07	BOEING	737	Wings - Fuel Tanks - Modification
US-2019-25-13	2020-01-06	ENGINE ALLIANCE LLC	GP7200	Engine - Low-Pressure Compressor Stage 1 Fan BladeS - Inspection / Replacement
US-2019-25-17	2020-01-06	BOEING	737	Indicating / Recording System - Airplane Flight Manual / Display Unit Software Errors - Revision
ISR-I-53-2019-12-6R1	2019-12-30	BOEING, ISRAEL AIRCRAFT INDUSTRIES	737, CAA Israel STC SA138, CAA Israel STC SA160, CAA Israel STC SA299, EASA STC 10015542, EASA STC 10016227, STC EASA.IM.A.S.01426, STC EASA.IM.A.S.02479	Loading Restrictions due to 9G Barrier Manufacturing Non-Compliance