



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|---|---|--|
| 2020-0089 | 2020-04-17 | AIRBUS | A380 | Nacelles / Pylons - Inboard Pylon Box at Rib 14 Fasteners - Inspection / Replacement |
| 2020-0088 | 2020-04-17 | AIRBUS | A380 | Electric and Electronic Common Installation - Ram Air Turbine Wiring Routing - Inspection |
| 2019-0179R1 | 2020-04-17 | BHE & ASSOCIATES, Ltd., BOMBARDIER, NEXTANT AEROSPACE LLC , ROCKWELL COLLINS, TEXTRON AVIATION INC. | EASA STC 10060629, EASA STC 10068943, FAA STC SA11136SC, FAA STC SA11219SC, CL-600 (Challenger), FAA STC ST04356CH, EASA STC 10056137, EASA STC 10056335, EASA STC 10056340, FAA STC SA01769WI , FAA STC SA01784WI , FAA STC SA01792WI , 200 (Super King Air), 300 (Super King Air), 525 (CitationJet), 90 (King Air) | Navigation - Airborne Collision Avoidance System Display Software - Update |
| CF-2020-11 | 2020-04-17 | BELL TEXTRON CANADA LTD (BTCL) | 429 | Flight Controls - Incorrectly Staked Directional Control Bellcrank Bearing |
| 2017-0134R2 | 2020-04-16 | AIRBUS HELICOPTERS | SA 330 / AS 332 / EC 225 | Time Limits / Maintenance Checks - Main Gearbox Particle Detector / Oil Filter / Oil Cooler - Inspection Main Rotor Drive - Epicyclic Module - Replacement / Modification / Reduced Service Life Limit |
| BR-2020-04-01 | 2020-04-16 | EMBRAER | EMB-545/-550 (Legacy 500) | Windows - Cockpit Side Windows - Inspection / Replacement |
| US-2020-08-01 | 2020-04-15 | GENERAL ELECTRIC | CF34 | Engine - Fan Blades - Removal / Replacement |
| 2020-0087 | 2020-04-15 | AIRBUS HELICOPTERS | SA 330 / AS 332 / EC 225 | Doors - Side Stairway Door Locking Safety Mechanism - Inspection / Reconditioning / Modification |
| US-2020-06-11 | 2020-04-14 | MD HELICOPTERS INC (MDHI) | 600N | Main Rotor Control - Main Rotor Blade Upper Control Collective / Longitudinal Link Assembly - Removal / Life Limit |
| CF-2020-09 | 2020-04-14 | BOMBARDIER | CL-600 (Regional Jet) | Landing Gear - General "Nose Landing Gear and Main Landing Gear Components Repaired by Bombardier Repair Engineering Orders Affected by Specific Airworthiness Limitation. |
| US-2020-07-51 | 2020-04-14 | INTERNATIONAL AERO ENGINES AG | V2500-()5 | [Final Rule] Engine - High Pressure Turbine 1st-Stage Disks - Removal |
| 2020-0086 | 2020-04-14 | AIRBUS HELICOPTERS | SA 330 / AS 332 / EC 225 | Tail Rotor - Hub Assembly - Inspection / Replacement |
| 2011-0164R3 | 2020-04-07 | AIRBUS HELICOPTERS | AS 350 / EC 130, AS 355 | Rotors Flight Control - Tail Rotor Control Stop Screws - Inspection |



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|------------|------------------------|--|
| CF-2020-08 | 2020-04-07 | BOMBARDIER | CL-600 (Regional Jet) | Ice and Rain Protection - Wing Anti-Ice System - Introduction of Safe Life Limit for Pneumatic Telescopic Duct |
| US-2020-04-15 | 2020-04-06 | BOEING | 757, 767 | Air Conditioning - High Flight Deck or Cabin Temperatures - Airplane Flight Manual Revision |
| 2020-0085 | 2020-04-06 | AIRBUS | A318, A319, A320, A321 | Powerplant - Aft Engine Mounts Retainers - Replacement |