



Publ. number	Issue Date	TC Holder	Type	Subject
2020-0010R3	2025-01-30	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Engine - De-Pairing Limitation
2019-0249R1	2025-01-30	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Engine - Intermediate Pressure Compressor Blades / Shafts - Inspection
CF-2025-07	2025-01-29	AIRBUS CANADA LP	BD-500 (A220 Series)	Flight Controls - Horizontal Stabilizer Trim Actuator (HSTA) - Incorrect Installation of the Interface Pin in the Upper Gimbal
2024-0152R1	2025-01-29	TECNAM, Costruzioni Aeronautiche	P2008 JC	Ignition - Advanced Start System - Deactivation
CF-2025-06	2025-01-27	BOMBARDIER	CL-600 (Challenger)	Auxiliary Power Unit (APU) - APU Muffler Drainage Blockage Causing Fuel Leakage Accumulation
CF-2025-05	2025-01-27	BOMBARDIER	CL-600 (Challenger)	Landing Gear - Uncommanded Steering
RA-2024-05-01R1	2025-01-27	LAVIA S.A.	PA-25 (Chincul), PA-25 (Pawnee), PA-25 (Puelche)	Corrosion found in the front and rear spars of wings and cracks found in the front spar
2025-0025	2025-01-23	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Equipment / Furnishings - Emergency Release Control of Cargo-Swing Installation - Inspection
GA8-12	2025-01-22	GA8 AIRVAN Pty Ltd (GippsAero)	GA8	Powerplant Instrumentation and Limitations - Maintenance and Operational Manual - Amendment
2025-0021R1	2025-01-22	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 7000	Engine - High Pressure Turbine Blades - Inspection
2025-0024	2025-01-22	ATR	ATR42, ATR72	Fire Protection - Aft Cargo Compartment Fire Extinguisher Distribution Piping - Functional Check
2025-0020R1	2025-01-22	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 900	Engine - Combustion Rear Inner Case Bolt - Replacement / Modification
2025-0023-E	2025-01-22	PIPISTREL VERTICAL SOLUTIONS d.o.o.	Virus SW	Flight Controls - Flaperon Bellcrank Bolt - Inspection
2025-0022	2025-01-21	GE AVIATION CZECH	H75, H80, H85, M601	Engine Fuel & Control - Fuel Control System - Additive Application
BR-2025-01-01	2025-01-20	EMBRAER S.A.	ERJ 190	Computerized Aeroplane Flight Manual Takeoff Calculation Module - Revision
CF-2025-04	2025-01-20	AIRBUS CANADA LP	BD-500 (A220 Series)	Electrical System Installation - Lavatory A Maintenance Panel - Harnesses Inadequately Secured