



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|---|--|---|
| 2025-0040 | 2025-02-14 | AIRBUS HELICOPTERS | H160 | Main Rotor - Rotating Scissors Spherical Bearings - Inspection |
| 2025-0038 | 2025-02-14 | MECAER AVIATION GROUP SpA | AMD-500N, NH-500D | Rotors Flight Control - Pilot Interconnecting Cyclic Pitch Torque Tube Assembly - Inspection |
| 2025-0039-E | 2025-02-14 | AIRBUS HELICOPTERS | EC175 | Fuselage - Pylon Reinforcement Fittings - Inspection |
| US-2025-01-08 | 2025-02-14 | BOEING | 747 | Equipment / Furnishings - Captain's and First Officer's Seats - Inspection / Check |
| 2025-0034 | 2025-02-12 | AIRBUS S.A.S. | A330 | Fire Protection - Engine Fire Extinguisher Bottles - Modification |
| 2025-0035 | 2025-02-12 | AIRBUS S.A.S. | A350 | Hydraulic Power - Engine Driven Pump - Software Update / Modification |
| 2025-0036 | 2025-02-12 | AIRBUS HELICOPTERS | AS 350 / EC 130 | Equipment / Furnishings - Cargo Hook Assembly - Inspection |
| CF-2025-08 | 2025-02-12 | PRATT & WHITNEY CANADA | PW545 | Engine - High Pressure Turbine (HPT) Disk - Improper Rework |
| 2025-0037 | 2025-02-12 | AIRBUS S.A.S. | A319, A320, A321 | Aircraft Flight Manual - Amendment |
| US-2025-02-13 | 2025-02-12 | BOEING, VT MOBILE AEROSPACE ENGINEERING | 757, EASA STC 10038822, EASA STC 10057068, FAA STC ST03562AT, FAA STC ST03952AT, FAA STC ST04242AT | Fuselage - Forward and Aft Hinge Areas of the Main Deck Cargo Door Cutout - Maintenance Record Check / Inspections |
| US-2025-02-05 | 2025-02-12 | BOEING | 747 | Landing Gear - Outer Cylinders - Replacement |
| 2025-0030 | 2025-02-10 | AIRBUS S.A.S. | A318, A319, A320, A321 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitations Items - Amendment |
| 2025-0031 | 2025-02-10 | AIRBUS S.A.S. | A318, A319, A320, A321 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 3 - Certification Maintenance Requirements - Amendment |
| 2025-0032 | 2025-02-10 | AIRBUS S.A.S. | A318, A319, A320, A321 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 4 - System Equipment Maintenance Requirements - Amendment |
| US-2025-01-09 | 2025-02-10 | BOEING | 787 | Windows - No. 1 Flight Compartment Windows - Replacement |



| Publ. number | Issue Date | TC Holder | Type | Subject |
|---------------|------------|-------------------------------------|--------------------------------|--|
| 2025-0033 | 2025-02-10 | AIRBUS S.A.S. | A318, A319, A320, A321 | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 5 - Fuel Airworthiness Limitations - Amendment |
| 2025-0028 | 2025-02-07 | AIRBUS HELICOPTERS DEUTSCHLAND | MBB-BK 117 | Main Rotor - Main Rotor Head - Inspection / Re-identification |
| 2025-0029 | 2025-02-07 | AIRBUS HELICOPTERS DEUTSCHLAND | MBB-BK 117 | Main Rotor - Swashplate - Inspection |
| 2025-0027 | 2025-02-05 | AIRBUS HELICOPTERS DEUTSCHLAND | MBB-BK 117 | Main Rotor - Swashplate Inner and Outer Ring Bolts - Inspection / Replacement |
| US-2025-01-06 | 2025-02-05 | BOEING | 767 | Equipment / Furnishings - Flight Crew Seats - Inspection / Check |
| US-2024-26-02 | 2025-02-04 | APPLIANCES | ATA 25 EQUIPMENT / FURNISHINGS | Pacific Scientific Company: Rotary Buckle Assemblies - Inspection / Replacement |
| 2007-0260-CN | 2025-02-04 | ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG | RB211 TRENT 700 | CANCELLED: Engine - Intermediate Pressure Turbine Bearing Oil Feed Tube - Inspection / Modification |
| US-2024-26-03 | 2025-02-03 | BOEING | 767 | Water / Waste - Potable Water System - Installation / Leakage Test |