



Publ. number	Issue Date	TC Holder	Type	Subject
2025-0235	2025-10-23	WSK PZL-SWIDNIK S.A.	PZL W-3A	Engine - Vibration Levels - Measurements / Inspections
2025-0233	2025-10-23	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Engine - High-Pressure Compressor / Mini-Disc Anti-Rotation Block - Inspection / Modification
2025-0234	2025-10-23	AIRBUS S.A.S.	A318, A319, A320, A321	Fire Protection - Fire Panel - Inspection
2025-0236	2025-10-23	AIRBUS S.A.S.	A300-600	Fuselage - Frame Base Fitting between Frames 41 and 46 - Inspection / Repair
2025-0232	2025-10-22	AIRBUS S.A.S.	A300-600ST (Beluga)	Wings - Centre Section Frame 40 Forward Fitting Radius at Tension Bolt Junction - Inspection / Repair
BR-2025-09-02	2025-10-22	EMBRAER S.A.	EMB-135	[Correction] Airworthiness Limitations (Certification Maintenance Requirements, Airworthiness Limitation Inspections, Fuel System Limitation Items, and Life Limited Items) - Revision
2025-0205R1	2025-10-22	ATR	ATR42, ATR72	Fuselage - Passenger Seat Tracks - Inspection / Replacement
2019-0044R1	2025-10-22	AIRBUS S.A.S.	A300-600	Wings - Centre Section Frame 40 Forward Fitting Radius at Tension Bolt Junction - Inspection / Repair
2025-0231	2025-10-21	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Fire Protection - Pyrotechnical Cartridge - Inspection
2025-0230-E	2025-10-21	SMA AERO ENGINES GmbH, TEXTRON AVIATION INC.	EASA STC 10013975, EASA STC 10016495, STC EASA IM.A.S.02857, STC EASA.A.S.00774, 182 (Skylane), F182	Powerplant - Turbocharger and Intercooler Hoses - Inspection/Replacement
2025-0229	2025-10-20	DASSAULT AVIATION	Falcon 7X	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2021-0281R3	2025-10-20	AIRBUS S.A.S.	A330	Aircraft Flight Manual / Engine Bleed Air System - Amendment / Pneumatic - Engine Bleed Air System - Maintenance Tasks
2025-0224	2025-10-16	AIRBUS S.A.S.	A310	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 / Damage Tolerant Airworthiness Limitations Items - Amendment
2025-0228	2025-10-16	DASSAULT AVIATION	Falcon 2000, Falcon 7X, Falcon 900EX	Standard Practices and Structures - DECOMATIC Titanium Bolts - Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
2025-0227	2025-10-16	AIRBUS HELICOPTERS	EC175	Main Rotor - Upper and Lower H Legs - Service Life Limit
ISR-I-05-2025-10-1	2025-10-16	GULFSTREAM (GALP)	G150	G150 Airworthiness Limitations Section Revision
2007-0201R1	2025-10-16	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 700	Engine - High Pressure and Intermediate Pressure Turbine Bearing Oil Vent Tubes - Inspection / Cleaning / Replacement
2025-0225-E	2025-10-16	SMA AERO ENGINES GmbH, TEXTRON AVIATION INC.	EASA STC 10013975, STC EASA.A.S.00774, 182 (Skylane), F182	SUPERSEDED BY EASA EMERGENCY AD 2025-0230-E
2025-0223	2025-10-15	ATR	ATR42, ATR72	Parking, Mooring and Storage - Mooring Procedure - Prohibition
CF-2025-50	2025-10-13	BOMBARDIER	BD-700	Flight Controls - Roll Control Input-Modules (RCIMs) Incorrect Installation
CF-2025-49	2025-10-13	BOMBARDIER	BD-700	Wings - Low Clearance Between Fuel Vent Tube Installation and Surrounding Systems and Structures in Right Wing
2025-0222	2025-10-13	APPLIANCES	ATA 35 OXYGEN	AEROSPACE & DEFENSE OXYGEN SYSTEMS SaS (Part of SAFRAN AEROSYSTEMS): Portable Breathing Equipment - Operational Instructions