


<b>EASA</b>	<b>COMMENT RESPONSE DOCUMENT</b>
	<b>EASA PAD No. 10-006</b> <b>[Published on 21 January 2010 and officially closed for comments on 18 February 2010]</b>

**Commenter 1 : FlyingGroup – Alain Lefebvre – 11/02/2010**

**Comment # 1**

Could you please do a precision regarding Dassault MOD 897?

Please let me know if only the part 1 of this MOD must be performed to answer of the requirement of this AD?

On my 7X, M937, M976, M1007, M1020 & M1022 have been implemented on production but only the part 1 is performed regarding the MOD 897.

***EASA response:***

Noted.

In the meantime, the Dassault MOD 897 has been withdrawn from the applicability paragraph of the AD and replaced by the specific list of aircraft serial numbers which do not have MOD 897 part 1 embodied. Please check new AD applicability to determine whether your Falcon 7X is concerned by this AD or not.