


EASA	NOTIFICATION OF A PROPOSAL TO ISSUE AN AIRWORTHINESS DIRECTIVE
	<p>PAD No.: 12-010</p> <p>Date: 08 February 2012</p> <p>Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.</p>
<p>In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below. All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation closing date indicated.</p>	
Type Approval Holder's Name : Fokker Services B.V.	Type/Model designation(s) : F28 Aeroplanes
TCDS Number : EASA.A.037	
Foreign AD : Not applicable	
Supersedure: This AD supersedes EASA AD 2011-0157 dated 25 August 2011.	
ATA 05	Time Limits / Maintenance Checks – Maintenance Requirements – Implementation
Manufacturer(s):	Fokker Aircraft B.V.
Applicability:	F28 Mark 0070 and Mark 0100 aeroplanes, all serial numbers
Reason:	<p>Fokker Services has published issue 3 of report SE-672 dated 3 January 2012 and issue 9 of report SE-SE-473 dated 11 January 2012, both part of the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness, referred to in Section 06, Appendix 1, of the Fokker 70/100 Maintenance Review Board (MRB) document. The complete ALS currently consists of:</p> <ul style="list-style-type: none"> - Certification Maintenance Requirements (CMRs) – report SE-473, issue 9 - Airworthiness Limitation Items (ALIs) and Safe Life Items (SLIs) – report SE-623, issue 8 - Fuel ALIs and Critical Design Configuration Control Limitations (CDCCLs) – report SE-672, issue 3 <p>The instructions contained in those reports have been identified as mandatory actions for continued airworthiness.</p> <p>For the reasons described above, this AD retains the requirements of EASA AD 2011-0157, which is superseded, and requires the implementation of the inspections and limitations as specified in the ALS of the Instructions for Continued Airworthiness, referred to in Section 06, Appendix 1 of the Fokker 70/100 MRB document, reports SE-473, SE-623 and SE-672 at the above-mentioned issues.</p>
Effective Date:	[TBD: 14 days after final AD issue date]

<p>Required Action(s) and Compliance Time(s):</p>	<p>Required as indicated, unless accomplished previously.</p> <p>(1) After the effective date of this AD, accomplish the following actions, as specified in Fokker Services Reports SE-473 issue 9 (CMRs), SE-623 issue 8 (ALIs and SLIs) and SE-672, issue 3 (Fuel ALIs and CDCCLs):</p> <p>(1.1) Replace each component before or upon reaching the applicable life limit, and</p> <p>(1.2) Within the thresholds and intervals, accomplish all applicable maintenance tasks.</p> <p>(2) In case of finding discrepancies (as defined in the ALS, reports SE-473, SE-623 and SE-672) during accomplishment of any task as required by paragraph (1) of this AD, within the applicable compliance time specified in the ALS, report SE-473, SE-623 or SE-672, as applicable, accomplish the applicable maintenance procedures for corrective actions in accordance with the approved maintenance documentation. If no compliance time is identified in the ALS, report SE-473, SE-623 or SE-672, as applicable, accomplish the applicable corrective actions before next flight. If a detected discrepancy is not identified in the ALS, report SE-473, SE-623 or SE-672, as applicable, before next flight, contact Fokker Services for approved instructions and accomplish those instructions accordingly.</p> <p>(3) Compliance with the requirements of paragraphs (1) and (2) of this AD can be demonstrated by:</p> <p>(3.1) Revising as follows the approved Aircraft Maintenance Programme (AMP) and standard practices on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane:</p> <p style="padding-left: 40px;">Incorporate the limitations, tasks and associated thresholds and intervals described in reports SE-473 (issue 9), SE-623 (issue 8) and SE-672 (issue 3),</p> <p style="padding-left: 40px;">and</p> <p>(3.2) Complying with the approved AMP described in paragraph (2.1) of this AD.</p>
<p>Ref. Publications:</p>	<p>Fokker 70/100 Instructions for Continued Airworthiness, ALS reports:</p> <p>SE-473 issue 9 dated 11 January 2012, SE-623 issue 8 dated 17 March 2011, and SE-672 issue 3 dated 3 January 2011.</p> <p>The use of later approved revisions of these reports is acceptable for compliance with the requirements of this AD.</p>
<p>Remarks :</p>	<p>1. This Proposed AD will be closed for consultation on 07 March 2012.</p> <p>2. Enquiries regarding this PAD should be referred to the Safety Information Section, Executive Directorate, EASA; E-mail ADs@easa.europa.eu.</p> <p>3. For any question concerning the technical content of the requirements in this PAD, please contact: Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL, Hoofddorp, The Netherlands; telephone +31-88-6280-350; facsimile +31-88-6280-111; e-mail: technicalservices@fokker.com. The referenced publication can be downloaded from www.myfokkerfleet.com</p>